

SERVICE INFORMATION

No. SI-E4-004

1. BASIC INFORMATION

1.1. SUBJECT

EECU venting element

1.2. ENGINES AFFECTED

Type: E4, all models


Serial Number: All

1.3. REASON

Engine behavior due to clogged venting element of EECU.

1.4. INFORMATION

During all time it has to be ensured that the venting element of the EECU (see figure below for position of the venting element) is not blocked and that no stagnant water can form above the venting element.



First Issue Date			Rev. No.		Revision Date		Page
27	Aug	2015	---	---	---	---	1-2



Service Information
No. SI-E4-004

Austro Engine GmbH
Rudolf-Diesel-Strasse 11
A-2700 Wiener Neustadt
Tel: +43 2622 23000
FAX: +43 2622 23000-2711

2. REMARKS

 **NOTE:** SI are used only:

- To distribute information from Austro Engine GmbH to our customers.
- To distribute applicable information/documents from our suppliers to our customers with additional information.

First Issue Date			Rev. No.	Revision Date				Page
27	Aug	2015	---	---	---	---	2-2	