



Service Information
No. SI-E4-007

Austro Engine GmbH
Rudolf-Diesel-Strasse 11
A-2700 Wiener Neustadt
Tel: +43 2622 23000
FAX: +43 2622 23000-2711

SERVICE INFORMATION

No. SI-E4-007

1. BASIC INFORMATION

1.1. SUBJECT

Proper handling of turbo charger

1.2. ENGINES AFFECTED

Type: E4, all models

Serial Number: All

1.3. REASON

Improper handling of the turbo charger could subsequently lead to mechanical failure of the turbo charger.

1.4. INFORMATION

Ensure proper and careful handling of the turbo charger when conducting maintenance works. Only use a rubber hammer when needed! Only gently tapping with the rubber hammer is allowed!

Replace the turbo charger in case of any damage caused by improper handling!

2. REMARKS

NOTE: SI are used only:

- To distribute information from Austro Engine GmbH to our customers.
- To distribute applicable information/documents from our suppliers to our customers with additional information.

First Issue Date			Rev. No.	Revision Date				Page
27	Sep	2016	---	---	---	---	1-1	