



Service Information  
No. SI-E4-009

Austro Engine GmbH  
Rudolf-Diesel-Strasse 11  
2700 Wiener Neustadt  
PHONE: +43 2622 23000  
FAX: +43 2622 23000-2711

# SERVICE INFORMATION

## No. SI-E4-009

### 1. BASIC INFORMATION

#### 1.1. SUBJECT

Two-Mass Flywheel and Hub

#### 1.2. ENGINES AFFECTED

Type: E4  
Model: E4, E4P  
Serial Number(s): all

#### 1.3. REASON

Austro Engine hereby advises to avoid the change of two-mass flywheels from twin engine aircraft (E4-B, E4-C and E4P-C engines) to single engine aircraft (E4-A engines).

#### 1.4. INFORMATION

On twin-engine aircrafts (E4-B, E4-C, E4P-C) specially in flight training environment the wear and tear of the two-mass flywheel is slightly higher then on single-engine aircrafts (E4-A). Due to this fact it should not happen that a used two-mass flywheel, which was already mounted on a twin – engine aircraft, shall be used or mounted on a single engine aircraft. This procedure is to provide additional safety margin under all circumstances.

### 2. REMARKS

**NOTE:** SI are used only:

- To distribute information from Austro Engine GmbH to our customers.
- To distribute applicable information/documents from our suppliers to our customers with additional information.

|                  |     |      |          |               |     |      |     |      |
|------------------|-----|------|----------|---------------|-----|------|-----|------|
| First Issue Date |     |      | Rev. No. | Revision Date |     |      |     | Page |
| 14               | Jun | 2017 | --       | --            | --- | ---- | 1-1 |      |