

TEMPORARY REVISION

OM-TR-MDC-E4-378

TBO extension of engine components

This Temporary Revision OM-TR-MDC-E4-378 is approved in conjunction with the Design Change Advisory MDC-E4-378 and is valid in conjunction with the latest revision of the Operation Manual (OM) until this Temporary Revision has been incorporated into the OM.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the OM.

The technical information contained in this document has been approved by EASA.

Doc. Nr.	Affected Section(S)	Affected Page(s)
E4.01.02	4	1a

Instruction:

- Print this document on yellow paper (single-sided)
- Insert this cover page as the first page of the OM
- Insert the other pages of this Temporary Revision adjacent to or in front of the corresponding OM pages

Issue date: 15.Jun.2016	TBO extension of engine components	COVERPAGE
-------------------------	------------------------------------	-----------

4. Operating Instructions

4.1 Engine Start Procedure

4.1.1 Pre-Start Inspection

The following text is added:

Check exhaust pipe for oil leakage from turbo charger.