

Mandatory Service Bulletin No. MSB-E4-002/2

Austro Engine GmbH Rudolf-Diesel-Strasse 11 A-2700 Wiener Neustadt Tel: +43 2622 23000 FAX: +43 2622 23000-2711

MANDATORY

SERVICE BULLETIN

No. MSB-E4-002/2 SUPERSEDES MSB No. MSB-E4-002/1

1. BASIC INFORMATION

1.1. SUBJECT

Configuration Specification of the E4 Engine Series

1.2. ENGINES AFFECTED

Type: E4 and E4P Engine

Serial numbers: all

1.3. REASON

According to E4 Type Certificate Data Sheet (TCDS), No. E.200, Chapter VI the engine model number may include suffixes to define minor engine changes related to installation specific configurations. These suffixes are declared within this MSB.

1.4. TIME OF COMPLIANCE

Not applicable.

1.5. CONCURRENT DOCUMENTS / REFERENCES

None.

1.6. OTHER PUBLICATIONS AFFECTED

None.

First Issue Date			Rev. No.	Revision Date			Page
13	Feb	2009	2	01	Apr	2015	1-4



Mandatory Service Bulletin No. MSB-E4-002/2

Austro Engine GmbH Rudolf-Diesel-Strasse 11 A-2700 Wiener Neustadt Tel: +43 2622 23000

FAX: +43 2622 23000-2711

2. TECHNICAL DETAILS

2.1. ACCOMPLISHMENT / INSTRUCTIONS

General: E4-x ... (suffix x could be A, B, C, ...)

The following table defines the actual E4 installation configurations.

Model	Serial Numbers	Configuration Specification	Remarks		
E4-A	E4-A-00001 and	Basic Configuration	for SW Versions refer to		
	subsequent		SB-003		
E4-B	E4-B-00001 and	Manifold intake opposite	for SW Versions refer to		
	subsequent	direction;	SB-003		
1		Different connecting angle of			
		turbocharger inlet hose;			
E4-C	E4-C-00001 and	Manifold intake opposite	for SW Versions refer to		
	subsequent	direction;	SB-003		
		Different connecting angle of			
		turbocharger inlet hose;			
		Different Assy Return Line;			
E4P-C	E4P-C-00001 and	Manifold intake opposite	for SW Versions refer to		
	subsequent	direction;	SB-003		
		Different connecting angle of			
		turbocharger inlet hose;			
		Different Assy Return Line;			
		Increased take-off power;			

2.2. ILLUSTRATIONS

None.

2.3. MASS (WEIGHT)

Not affected.

First Issue Date			Rev. No.	Revision Date			Page
13	Feb	2009	2	01	Apr	2015	2-4



Mandatory Service Bulletin No. MSB-E4-002/2

Austro Engine GmbH Rudolf-Diesel-Strasse 11 A-2700 Wiener Neustadt Tel: +43 2622 23000 FAX: +43 2622 23000-2711

2.4. APPROVAL STATEMENT

The technical content of this document has been approved under the authority of DOA No. EASA.21J.399.

3. PLANNING INFORMATION

3.1. MATERIAL & AVAILABILITY

Not applicable.

3.2. SPECIAL TOOLS

Not applicable.

3.3. LABOR EFFORT

Not applicable.

First Issue Date			Rev. No.		Revision Date			Page
13	Feb	2009	2	01	Apr	2015		3-4



Mandatory Service Bulletin No. MSB-E4-002/2

Austro Engine GmbH Rudolf-Diesel-Strasse 11 A-2700 Wiener Neustadt Tel: +43 2622 23000

FAX: +43 2622 23000-2711

4. REMARKS

■ NOTE:

- All measures must be carried out by a certified engine station and certified engine mechanic.
- The accomplishment of the instructions shown under chapter 2.1 must be confirmed in the respective engine log book.
- The accomplishment of the instructions must be carried out within the time of compliance according chapter 1.4.
- o In case of doubt please contact the Austro Engine GmbH After Sales Support (e-mail: service@austroengine.at; Tel: +43 2622 23000 2525).

5. EXPLANATORY NOTES

5.1. SYMBOL EXPLANATION

<u>∧</u> wai

WARNING: Disregarding these safety rules can cause personal injury or even death

CW/TON

CAUTION: Disregarding these special instructions and safety measures can cause

damage to the engine or other components.

NOTE: Additional note or instruction for better understanding of an instruction

6. APPENDIX

None.

First Issue Date			Rev. No.	Revision Date			Page
13	Feb	2009	2	01	Apr	2015	4-4