

TEMPORARY REVISION

OHMG-TR-MDC-E4-369

General Amendments

This Temporary Revision OHMG-TR-MDC-E4-369 is approved in conjunction with the Design Change Advisory MDC-E4-369 and is valid in conjunction with the latest revision of the Overhaul Manual-Gearbox (OHMG) until this Temporary Revision has been incorporated into the OHMG.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the OHMG.

The technical information contained in this document has been approved under the authority of DOA ref. EASA.21J.0399.

Doc. Nr.	Affected Section(s)	Affected Page(s)s
E4.12.02	1	1a
	2	1a
	3	2a, 13a

Instruction:


- Print this document on yellow paper (single-sided)
- Insert this cover page as the first page of the OHMG
- Insert the other pages of this Temporary Revision adjacent to or in front of the corresponding OHMG pages

1. Introduction

1.1 Gearbox revision

1.1.1 Gearbox with revision 070 and 080

The existing table is amended to read:





**OVERHAUL MANUAL
Gearbox**

E4.12.02
OHMG-TR-MDC-E4-369

2. General Procedures

2.2 Cleaning

Following text is removed:

Contact Austro Engine GmbH in case of doubt.

3. Repair procedures

3.3 Inspections of gears and shafts

The existing text is replaced by the following:

Inspect all gears for signs of wear, especially pitting. If signs of wear or pitting can be found, the concerning gear has to be replaced by a new gear. For proper part identification refer to the part number as listed in the Sub-Assembly sections in Section 5.



**OVERHAUL MANUAL
Gearbox**

E4.12.02
OHMG-TR-MDC-E4-369

3.4 Inspection of housing parts

Following text is removed:

~~In case of doubt discard concerning part or contact Austro Engine GmbH.~~